



Town of Weston

Tree Risk Assessment Report

Inspection ID: 9370

PREPARED FOR:

Town of Weston
56 Norfield Road
Weston, Connecticut 06883

PREPARED BY:

Casey Tresp
ISA Certified Arborist #NE-1082A
Connecticut Arborist #S-6009
CTSP #02464
Tree Risk Assessment Qualified

PROVIDED BY:

Ryan O'Leary
ISA Certified Arborist #NE-7509A
Connecticut Arborist #S-6152
CTSP #03143
Tree Risk Assessment Qualified
Bartlett Tree Experts
476 Canal St.
Stamford, Connecticut 06902



Submitted on May 23, 2023
© The F.A. Bartlett Tree Expert Company

Summary

The red oak (*Quercus rubra*) located at the corner of Norfield Road and Norfield Farm Lane of the Town of Weston property was assessed for risk on May 17, 2023 by Casey Tresp. Using the methods outlined in this report and the results of the examination of this tree, it is my professional judgment that this tree has a **moderate risk rating**.

Mitigation is recommended for the tree parts listed below.

Tree Part	Mitigation Options	Estimated Residual Risk
Trunk	Remove tree to reduce the risk of stem, branch, and root failures	Low

Tree risk assessment definitions are provided at the end of this report to help with understanding the terminology and with selecting the level of risk you are comfortable with when making decisions on your tree care needs.

Assignment

Commercial arborist representative Ryan O'Leary was contracted by Town of Weston to assess the risk of the red oak located at the corner of Norfield Road and Norfield Farm Lane. Based on conversation, the following was agreed:

1. Perform a Level 2 basic and Level 3 advanced assessment (as defined in the *International Society of Arboriculture's (ISA's) Best Management Practices (BMP) for Tree Risk Assessment* and the *ANSI A300 Part 9 Standard for Tree Risk Assessment*). The limits of the assessment were discussed.
2. Make recommendations to reduce risk where appropriate.
3. Provide a written report that documents the level of risk based on tree and site conditions observed and discussed at the time of the inspection.

Assessment Procedures

The risk of root, root collar, trunk, crown and branch failure for the red oak via a ground-based and aerial assessment was performed. In addition, branches had an advanced assessment for failure performed using resistance drilling, the trunk had an advanced assessment for failure performed using resistance drilling and the roots and root collar had an advanced assessment for failure performed using resistance drilling. The assessments occurred on May 17, 2023 and followed the *International Society of Arboriculture's (ISA) Best Management Practices for Tree Risk Assessment and American National Standards Institute A300 Tree Risk Assessment Standard*).

Tree risk ratings are derived from a combination of three factors: the likelihood of failure, the likelihood of the failed tree part impacting a target, and the consequences of the target being struck. These factors are then used to categorize tree risk as extreme, high, moderate, or low. The factors used to define your risk rating are identified in this report.

Tools used in the assessment included: IML Resi PD400, rubber mallet, tape measure, dbh tape, aerial lift.

In addition, resistance drilling was used to identify the potential loss of structural integrity within the branch, trunk and roots, and provide images used for analysis within this report. The device uses a small diameter drill bit to drill into the tree and measure the amount of resistance encountered. The drill bit will encounter more resistance in wood that is intact and not structurally compromised. The drill bit will move easily through compromised areas such as a crack, cavity, decay, or void, causing a drop in resistance. The amount of resistance measured is presented as a graphic image from areas with high structural integrity to areas of no structural integrity.

Observations

The following observations were made by Casey Tresp during the tree inspection conducted on May 17, 2023:

- Tree species: red oak (*Quercus rubra*)
- Tree trunk diameter (DBH): 100 in.

Only the following high value targets within the target zone were considered. Other targets will be considered upon request.

1. People near the tree,
2. Power lines,
3. Vehicles

The large multi-stem, mature red oak is located at the corner of Norfield Road, and Norfield Farm Lane. The tree currently has three main trunks extending from the base of the tree and a large area where a fourth trunk was removed some time in the past. The base of the tree is within five inches of the edge of Norfield road. A noticeable wound from the removal of a large diameter limb on the south side of the main stem was observed. The area around the wound appears to have been cut flush against the trunk displaying an open cavity with visible signs of decay. The cavity measures 48 inches at the widest point. To the west of the removed leader a 39-inch vertical seam connects with a 13-inch lateral crack. The 13-inch lateral cracks depth was measured at five inches until hitting an obstruction. Movement of the seam was observed in light wind. Fungal fruiting bodies were found on the east side of the root flare. The main union appeared filled with organic material that was covering another cavity. An adventitious root was found under the organic material. The cavity in the center of the main union had a depth of 24 inches before an obstruction. An additional open cavity was observed and measured 51 inches in depth until obstruction. Signs of wood boring insects and woodpecker activity were observed.

Dead limbs up to four inches in diameter were observed over Norfield road. Multiple cabling systems were observed that appear to be under extreme load and undersized for the diameter of the material being supported.

Photographs of the tree and specific defects may be found below.

Tree Risk Assessment

After discussing the site's usage and **occupancy rates** throughout the course of the year with you, combined with my observations during the assessment, we determined that within the tree's **target zone**:

- People near the tree was an occasional target,
- Power lines was a constant target, and
- Vehicles were an occasional target

In determining the risk ratings, I considered a tree or tree part failure impacting a person to have one of the highest consequences, either **significant** or **severe**.

I considered a tree or tree part failure impacting a structure as having **severe** consequences.

I used a time frame of one year when I assessed the likelihood of tree or tree part failure. Following industry standards, the time frame is one factor used in the equation to determine tree risk. Trees and sites change on a daily basis. You should not consider this time frame a "guarantee period" for the risk assessment or that the tree will not fail or is safe within this time frame.

The main concerns observed during the assessment and their associated risk ratings are provided in the following paragraph. Information not specifically summarized was not considered a significant factor at the time of assessment.

The overall risk rating for this tree is considered moderate, indicated by the highest likelihood of failure for the tree parts assessed which is probable, the likelihood of impacting a target listed above is medium and the consequences of the failure and impact could be severe. If this level of risk is not acceptable to you, then mitigation actions should be taken to reduce the risk associated with this tree.

Discussion

The tree is recommended for removal as soon as possible.

Tree cable systems are supplemental support for weak unions in trees. There is no guarantee that failure will not occur when installed. The tree is showing signs of a critical loss of structurally sound material. When cable systems are installed, the tree continues to grow adding additional weight and stress to the support structures. Evidence of overloading can cause deformation of hardware as observed in cable terminations in this tree. The data obtained from the IML RESI PD400 has been interpreted as having a significant loss of structurally sound material. No mitigation will reduce the assigned risk rating if the tree is to remain. The tree is recommended for removal as soon as possible.

Mitigation is recommended for the tree parts listed below.

Tree Part	Mitigation Options	Estimated Residual Risk
Trunk	Remove tree to reduce the risk of stem, branch, and root failures	Low

All recommended work should be performed by qualified arborists and in accordance with industry accepted standards and best management practices set forth by the *American National Standards Institute* and the *International Society of Arboriculture*.

Limitations

Assignment

My assessment of the designated tree on Town of Weston's property was based on a single site visit on May 17, 2023. All photographs, samples, and readings, if applicable, were taken at the time the assessment was performed.

The assessment was limited to the visible and accessible tree parts described in the assignment.

Resistance Drilling

Resistance drilling devices can provide sophisticated results related to tree structure. This is done by measuring the amount of resistance the drill bit encounters. However, as with any higher-level technology, the amount of structural integrity loss shown can vary based on the version of the program software used. Therefore, this technology can be limited and should not be used by the tree owner/manager as the sole decision-making criteria, but rather one of many factors used in the decision-making process.

Tree Risk Assessments

It is important for the tree owner or manager to know and understand that all trees pose some degree of risk from failure or other conditions. The information and recommendations within this report have been derived from the level of tree risk assessment identified in this report, using the information and practices outlined in the *International Society of Arboriculture's Best Management Practices for Tree Risk Assessment and Assessment and American National Standards Institute A300 Tree Risk Assessment Standard*, as well as the information available at the time of the inspection. However, the overall tree risk rating, the mitigation recommendations, or any other conclusions do not preclude the possibility of failure from undetected conditions, weather events, or other acts of man or nature. Trees can unpredictably fail even if no defects or other conditions are present. Tree failure can cause adjacent trees to fail resulting in a "domino effect" that impacts targets outside the foreseeable target zone of this tree. It is the responsibility of the tree owner or manager to schedule repeat or advanced assessments, determine actions, and implement follow up recommendations, monitoring and/or mitigation.

Bartlett Tree Experts can make no warranty or guarantee whatsoever regarding the safety of any tree, trees, or parts of trees, regardless of the level of tree risk assessment provided, the risk rating, or the residual risk rating after mitigation. The information in this report should not be considered as making safety, legal, architectural, engineering, landscape architectural, land surveying advice or other professional advice. This information is solely for the use of the tree

owner and manager to assist in the decision-making process regarding the management of their tree or trees. Tree risk assessments are simply tools which should be used in conjunction with the owner or tree manager's knowledge, other information and observations related to the specific tree or trees discussed, and sound decision making.

Thank you for the opportunity to provide this information. Please contact me if you wish to review these results or discuss the next steps to take with mitigation, or if I can be of any other service in the management of your landscape.

Casey Tresp

ISA Certified Arborist #NE-1082A
Connecticut Arborist #S-6009
Tree Risk Assessment Qualified
CTSP #02464

Photographs:



Image of assessed tree's location.



View of assessed red oak looking east.

Image of assessed red oak.



View of main stem with cavity looking north.



View of root flare and flush cut on main stem looking west.



Image of 39-inch vertical seam along main stem.



Image of 13-inch long horizontal crack along main stem.



Image of depth of lateral crack.



Image of fungal fruiting body on east side of root flare. (Circled in yellow)



Image of main union with organic material concealing the cavity. An adventitious root from the 45-inch leader is circled in red.



Image showing depth of cavity at main union at 51 inches.



Image of a deformed 1/4" thimble installed in the crown of the tree.



Image of a second deformed ¼” thimble.




Image of multiple support anchors in 45-inch leader over Norfield road.

IML RESI PD400 data:

Measuring / object data

Measurement no.:	24	Speed	: 3000 r/min	Diameter:	
ID number	: NORFIELD RD red oak	Needle state:	--	Level	:
Drilling depth	: 15.78 in	Tilt	: 0°	Direction:	
Date	: 17.05.2023	Offset	: 106 / 274	Species	:
Time	: 10:00:08	Avg. curve	: off / off	Location	:
Feed	: 40 in/min	Name	:		



Assessment

■	From 0,00 in to 1,50 in : Bark
■	From 1,50 in to 15,78 in : Stable


Comment

6" above grade at 0 degrees

IML RESI PD400 data from six inches above grade drilled at 0 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	25	Speed	: 3000 r/min	Diameter:	
ID number	: NORFIELD RD red oak	Needle state:	---	Level	:
Drilling depth	: 15.78 in	Tilt	: -6°	Direction:	
Date	: 17.05.2023	Offset	: 106 / 270	Species	:
Time	: 10:01:16	Avg. curve	: off / off	Location	:
Feed	: 40 in/min	Name	:		



Assessment

■	From 0,00 in to 1,40 in : Bark
■	From 1,40 in to 15,78 in : Stable


Comment

6" above grade at 32 degrees

IML RESI PD400 data from six inches above grade drilled at 32 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	26	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	-2°	Direction:	
Date :	17.05.2023	Offset :	105 / 266	Species :	
Time :	10:02:13	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 1,10 in : Bark
■	From 1,10 in to 15,78 in : Stable


Comment

6" above grade at 64 degrees

IML RESI PD400 data from six inches above grade drilled at 64 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	27	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	-6°	Direction:	
Date :	17.05.2023	Offset :	112 / 267	Species :	
Time :	10:03:28	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,50 in :	Bark
From 0,50 in to 8,00 in :	Compromised
From 8,00 in to 13,00 in :	Stable
From 13,00 in to 15,77 in :	Compromised


Comment

6" above grade at 96 degrees

IML RESI PD400 data from six inches above grade drilled at 96 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	28	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,76 in	Tilt :	-4°	Direction:	
Date :	17.05.2023	Offset :	114 / 264	Species :	
Time :	10:04:40	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

- From 1,50 in to 3,30 in : Compromised
- From 3,30 in to 4,25 in : Stable
- From 4,25 in to 15,76 in : Compromised


Comment

6" above grade at 128 degrees

IML RESI PD400 data from six inches above grade drilled at 128 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	29	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	119 / 260	Species :	
Time :	10:05:56	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,60 in to 2,50 in :	Stable
From 2,50 in to 3,75 in :	Compromised
From 3,75 in to 5,80 in :	Stable
From 5,80 in to 15,77 in :	Compromised


Comment

6" above grade at 160 degrees

IML RESI PD400 data from six inches above grade drilled at 160 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	30	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	--	Level :	
Drilling depth :	15.77 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	115 / 261	Species :	
Time :	10:07:01	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 0,50 in : Bark
■	From 0,50 in to 4,20 in : Stable
■	From 4,20 in to 15,77 in : Compromised


Comment

6" above grade at 192 degrees

IML RESI PD400 data from six inches above grade drilled at 192 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.: 31	Speed : 3000 r/min	Diameter:
ID number : NORFIELD RD red oak	Needle state: ---	Level :
Drilling depth : 15,77 in	Tilt : 0°	Direction:
Date : 17.05.2023	Offset : 124 / 261	Species :
Time : 10:08:28	Avg. curve : off / off	Location :
Feed : 40 in/min		Name :



Assessment

From 0,00 in to 1,40 in : Bark
From 1,40 in to 4,45 in : Stable
From 4,45 in to 5,50 in : Compromised
From 5,50 in to 13,00 in : Stable
From 13,00 in to 15,77 in : Compromised


Comment

6" above grade at 224 degrees

IML RESI PD400 data from six inches above grade drilled at 224 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	32	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,76 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	122 / 262	Species :	
Time :	10:10:02	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,50 in :	Bark
From 0,50 in to 7,60 in :	Compromised
From 7,60 in to 8,50 in :	Stable
From 8,50 in to 10,60 in :	Compromised
From 10,60 in to 12,20 in :	Stable
From 12,20 in to 14,25 in :	Compromised


Comment

6" above grade at 256 degrees

IML RESI PD400 data from six inches above grade drilled at 256 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	33	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	103 / 262	Species :	
Time :	10:11:36	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 1,25 in :	Bark
From 1,25 in to 7,35 in :	Stable
From 7,35 in to 12,00 in :	Compromised
From 12,00 in to 15,78 in :	Stable


Comment

6" above grade at 288 degrees

IML RESI PD400 data from six inches above grade drilled at 288 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	35	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	-2°	Direction:	
Date :	17.05.2023	Offset :	122 / 296	Species :	
Time :	10:14:42	Avg. curve :	off / off	Location:	
Feed :	40 in/min	Name :			



Assessment

- From 0,00 in to 1,25 in : Bark
- From 1,25 in to 15,78 in : Stable


Comment

6" above grade at 352 degrees

IML RESI PD400 data from six inches above grade drilled at 352 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	12	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	112 / 297	Species :	
Time :	09:41:52	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,60 in :	Bark
From 0,60 in to 3,60 in :	Stable
From 3,60 in to 5,70 in :	Compromised
From 5,70 in to 15,78 in :	Stable


Comment

4.5' above grade at 0 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 0 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	13	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	-3°	Direction:	
Date :	17.05.2023	Offset :	103 / 285	Species :	
Time :	09:43:29	Avg. curve :	off / off	Location:	
Feed :	40 in/min			Name :	



Assessment

■	From 0,00 in to 0,80 in : Bark
■	From 0,80 in to 15,77 in : Stable


Comment

4.5' above grade at 32 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 32 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	14	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	104 / 287	Species :	
Time :	09:44:54	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 0,80 in : Bark
■	From 0,80 in to 12,00 in : Stable
■	From 12,00 in to 15,77 in : Compromised


Comment

4.5' above grade at 64 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 64 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	15	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	104 / 283	Species :	
Time :	09:46:18	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 1,40 in : Bark
■	From 1,40 in to 15,78 in : Stable


Comment

4.5' above grade at 96 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 96 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	16	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	--	Level :	
Drilling depth :	11.59 in	Tilt :	+2°	Direction:	
Date :	17.05.2023	Offset :	111 / 358	Species :	
Time :	09:47:56	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,50 in :	Stable
From 0,50 in to 1,35 in :	Compromised
From 1,50 in to 2,60 in :	Compromised
From 3,55 in to 5,15 in :	Compromised
From 5,80 in to 6,60 in :	Compromised
From 7,90 in to 11,59 in :	Compromised


Comment

4.5' above grade at 128 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 128 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	17	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15.77 in	Tilt :	+2°	Direction:	
Date :	17.05.2023	Offset :	110 / 281	Species :	
Time :	09:49:11	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 0,50 in : Stable
■	From 0,50 in to 2,25 in : Compromised
■	From 2,25 in to 6,25 in : Stable
■	From 6,25 in to 15,77 in : Compromised


Comment

4.5' above grade at 160 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 160 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	18	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	105 / 278	Species :	
Time :	09:50:31	Avg. curve :	off / off	Location :	
Feed :	40 in/min			Name :	



Assessment

From 0,00 in to 0,80 in :	Bark
From 0,80 in to 4,30 in :	Stable
From 4,30 in to 5,00 in :	Compromised
From 5,00 in to 15,78 in :	Stable


Comment

4.5' above grade at 192 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 192 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	19	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	+1°	Direction:	
Date :	17.05.2023	Offset :	119 / 276	Species :	
Time :	09:52:03	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,70 in :	Bark
From 0,70 in to 4,25 in :	Stable
From 4,25 in to 5,00 in :	Compromised
From 5,00 in to 5,80 in :	Stable
From 5,80 in to 6,50 in :	Compromised
From 6,50 in to 15,78 in :	Stable


Comment

4.5' above grade at 224 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 224 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	20	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	+1°	Direction:	
Date :	17.05.2023	Offset :	122 / 276	Species :	
Time :	09:53:51	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 0,60 in :	Bark
■	From 0,60 in to 2,45 in :	Compromised
■	From 2,45 in to 8,00 in :	Stable
■	From 8,00 in to 15,78 in :	Compromised


Comment

4.5' above grade at 256 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 256 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	21	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,76 in	Tilt :	-1°	Direction:	
Date :	17.05.2023	Offset :	123 / 273	Species :	
Time :	09:55:40	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 1,00 in : Bark
■	From 1,00 in to 12,10 in : Stable
■	From 12,10 in to 15,76 in : Compromised


Comment

4.5' above grade at 288 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 288 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	22	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	107 / 274	Species :	
Time :	09:57:11	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

■	From 0,00 in to 1,00 in :	Bark
■	From 1,00 in to 2,90 in :	Stable
■	From 2,90 in to 3,60 in :	Compromised
■	From 3,60 in to 15,78 in :	Stable


Comment

4.5' above grade at 320 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 320 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	23	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	106 / 294	Species :	
Time :	09:58:39	Avg. curve :	off / off	Location :	
Feed :	40 in/min			Name :	



Assessment

■	From 0,00 in to 1,00 in : Bark
■	From 1,00 in to 15,78 in : Stable


Comment

4.5' above grade at 352 degrees

IML RESI PD400 data from four- and one-half foot above grade drilled at 352 degrees. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	36	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	-2°	Direction:	
Date :	17.05.2023	Offset :	104 / 268	Species :	
Time :	10:30:45	Avg. curve :	off / off	Location :	
Feed :	40 in/min			Name :	



Assessment

From 0,00 in to 0,80 in :	Bark
From 0,80 in to 7,00 in :	Stable
From 7,00 in to 8,00 in :	Compromised
From 8,00 in to 15,77 in :	Stable


Comment

45" leader growing towards road at 0 degrees above main union

IML RESI PD400 data from 45-inch leader growing towards Norfield road drilled at 0 degrees above the main union. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	37	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	-15°	Direction:	
Date :	17.05.2023	Offset :	115 / 269	Species :	
Time :	10:32:49	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

From 0,00 in to 0,90 in :	Bark
From 0,90 in to 6,15 in :	Stable
From 6,15 in to 15,77 in :	Compromised


Comment

45" leader growing towards road at 72 degrees above main union

IML RESI PD400 data from 45-inch leader growing towards Norfield road drilled at 72 degrees above the main union. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	38	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,78 in	Tilt :	0°	Direction:	
Date :	17.05.2023	Offset :	102 / 271	Species :	
Time :	10:34:33	Avg. curve :	off / off	Location :	
Feed :	40 in/min			Name :	



Assessment

■	From 0,00 in to 0,40 in : Bark
■	From 0,40 in to 15,78 in : Stable
■	From 0,00 in to 0,00 in : Compromised


Comment

45" leader growing towards road at 144 degrees above main union

IML RESI PD400 data from 45-inch leader growing towards Norfield road drilled at 144 degrees above the main union. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	39	Speed :	3000 r/min	Diameter:	
ID number :	NORFIELD RD red oak	Needle state:	---	Level :	
Drilling depth :	15,77 in	Tilt :	+9°	Direction:	
Date :	17.05.2023	Offset :	98 / 257	Species :	
Time :	10:36:00	Avg. curve :	off / off	Location :	
Feed :	40 in/min	Name :			



Assessment

- From 0,00 in to 1,20 in : Bark
- From 1,20 in to 15,77 in : Stable


Comment

45" leader growing towards road at 216 degrees above main union

IML RESI PD400 data from 45-inch leader growing towards Norfield road drilled at 216 degrees above the main union. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.

Measuring / object data

Measurement no.:	40	Speed	: 3000 r/min	Diameter:	
ID number	: NORFIELD RD red oak	Needle state:	---	Level	:
Drilling depth	: 15,76 in	Tilt	: -1°	Direction:	
Date	: 17.05.2023	Offset	: 98 / 268	Species	:
Time	: 10:37:10	Avg. curve	: off / off	Location	:
Feed	: 40 in/min	Name	:		



Assessment

■	From 0,00 in to 1,00 in : Bark
■	From 1,00 in to 8,50 in : Stable
■	From 8,50 in to 15,76 in : Compromised

Comment

45" leader growing towards road at 288 degrees above main union

IML RESI PD400 data from 45-inch leader growing towards Norfield road drilled at 288 degrees above the main union. Routine peaks and valleys in the reading indicate structurally functional wood. Where the resistance decreases or becomes erratic decay is assumed.



Tree Risk Assessment Vocabulary

Tree risk assessment has a unique set of terminology with specific meanings. A complete list of tree risk vocabulary and procedures may be found in the International Society of Arboriculture's (ISA) *Best Management Practice (BMP) for Tree Risk Assessment* or the *American National Standards Institute (ANSI) A300 Tree Risk Assessment Standard*. The following information is provided to assist the owner/client with understanding some of the common industry phrases or language, and some of the procedures and methodologies associated with the industry language used in the proposal and/or report.

Vocabulary Used Throughout Proposals and Reports

Inspection interval is the recommended amount of time between inspections or assessments.

Occupancy rates categorize the estimated time a target is physically within a target zone. Occupancy rate is classified as rare, occasional, frequent, or constant.

Overall risk rating is the highest individual risk identified for the tree.

Residual risk is the estimated level of risk that will remain after the recommended mitigation efforts to reduce the risk have been made. This estimate is provided to help the client understand that some level of risk may still exist and plan appropriately for future risk management.

Risk is the likelihood of an event and its consequences.

Risk rating for a tree or tree part is the combination of the likelihood of failure, the likelihood of impact, and the consequences.

Time frame is the period the assessor uses in which to estimate the likelihood of failure in all categories except the "imminent" category. The use of a time frame is meant solely to help the assessor better determine the portions of the risk analysis which are time dependent. The owner/client should never consider the time frame a "guarantee period" for the risk assessment or that the tree will not fail or is safe within the stated time frame.

Targets are people, property, or activities that could be injured, damaged or disrupted by a tree or tree part failure.

Target occupancy rates are typically identified based on information obtained from the owner/client prior to conducting the assessment, as well as information gained during the limited time the assessor evaluates the tree and site. Targets, target zones, and occupancy rates may be adjusted based on observations during the assessment.

Target zones are the areas where a tree or tree part is likely to land if it were to fail. The target zone(s) is determined in the field at the time of the assessment.

Trees can generally be defined as a woody perennial plant with a single trunk, defined crown, and will reach a minimum height of 15 feet at maturity.

Tree parts include branches, fruit, and trunks.

Tree risk is the likelihood of a tree failure impacting a target and the severity of the consequences.

Tree risk assessment is the systematic process used to identify, analyze, and evaluate tree risk. Tree risk assessments are conducted to assist the tree owner or client in better understanding the risk their trees pose so they can make management decisions to reduce or minimize those risks. Tree risk assessments focus on evaluating the structural integrity of the tree crown, branches, trunks, and roots and root collar.

Tree risk assessors are trained arborists or qualified professionals with experience in performing tree risk assessments.

Vocabulary Used to Communicate Occupancy Rates

Constant indicates a target is present in the target zone at nearly all times, 24 hours a day, seven days a week.

Frequent indicates a target is present in the target zone for a large portion of the day or week.

Occasional indicates a target is present in the target zone infrequently or irregularly.

Rare indicates a target zone that is not commonly used by people or other mobile/movable targets.

Vocabulary Used to Communicate the Likelihood of Failure

Imminent indicates that failure has started or is most likely to occur in the near future, even if there is no significant wind or increased load.

Probable indicates that failure may be expected under normal weather conditions within the specified time frame.

Possible indicates that failure could occur, but is unlikely under normal weather conditions within the specified time frame.

Improbable indicates that failure is not likely during normal weather conditions, and it may not fail in extreme weather conditions within the specified time frame.

Vocabulary Used to Communicate the Likelihood of a Failure Impacting a Target

Very likely to impact a target is reached by an imminent likelihood of failure and high likelihood of impact.

Likely to impact a target can be reached by an imminent likelihood of failure and medium likelihood of impact; or probable likelihood of failure and high likelihood of impact.

Somewhat likely to impact a target can be reached by one of the following combinations; an imminent likelihood of failure and low likelihood of impact; probable likelihood of failure and medium likelihood of impact; or possible likelihood of failure and high likelihood of impact.

Unlikely to impact a target can be reached by one of the following combinations; a possible or probable likelihood of failure and low likelihood of impact; possible likelihood of failure and medium likelihood of impact; improbable likelihood of failure with any likelihood of impact rating; or any likelihood of failure rating with very low likelihood of impact.

Vocabulary Used to Communicate the Consequences of Failure and Impact

Severe consequences could involve serious personal injury or death, high-value property damage, or major disruption to important activities.

Significant consequences are those that could involve substantial personal injury, property damage of moderate to high value, or considerable disruption of activities.

Minor consequences are those that are believed will only cause minor personal injury, low-to-moderate-value property damage, or small disruption of activities.

Negligible consequences are those that are believed will not result in personal injury, will only involve low-value property damage, or disruptions that can be replaced or repaired.

Vocabulary Used to Communicate Overall Risk Ratings

Extreme risk applies in situations in which failure is imminent, there is a high likelihood of impacting the target, and the consequences of the failure are severe.

High risk situations are those for which consequences are significant and likelihood is very likely or likely; or consequences are severe and likelihood is likely.

Moderate risk situations are those for which consequences are minor and likelihood is very likely or likely; or likelihood is somewhat likely and consequences are significant or severe.

Low risk situations are those for which consequences are negligible and likelihood is unlikely; or consequences are minor and likelihood is somewhat likely.

Explanation of Tree Risk Levels

The three levels of tree risk assessment defined in the ANSI A300 Tree Risk Assessment Standard are:

I. Level 1: Limited Visual Assessment

This level of assessment provides a visual assessment from a defined perspective (e.g., from the sidewalk, street, or aerial view) of an individual tree or population of trees to assess risk to specified targets from obvious defects or specified conditions.

Level 1 assessments are typically performed to quickly assess large populations of trees or conduct a rapid assessment of an individual tree. The assessor views only one side of the tree while walking on a sidewalk, being unable to access a neighboring property, looking from a slow-moving car, or from above with a drone, helicopter, or airplane.

A Level 1 assessment requires the client to identify the location and/or selection criteria of trees to be assessed. The assessor may:

1. Determine the most efficient route and document the route taken.
2. Assess the tree(s) within the area from the defined perspective (e.g., walk-by or drive-by).
3. Record the location of trees that meet the defined criteria (e.g., significant defects or other conditions of concern).
4. Evaluate the risk (risk rating is optional).
5. Identify trees requiring a higher level of assessment (Level 2 or Level 3) and/or prompt action.
6. Submit risk mitigation recommendations and/or a report.

Limitations: Level 1 assessments are the least thorough means of assessment. They are typically from one perspective, such as a walk-by, a drive-by, or aerial view. This level of assessment is most commonly used to prioritize higher-risk trees within larger groups of trees when there are budgetary, time, or other management constraints. Some defects or conditions will not be visible to the inspector, nor will all conditions visible at all times of the year; therefore, not all higher-risk trees will be accurately identified. In addition, the assessment may not provide enough information to assign a risk rating, make a risk mitigation recommendation, or determine residual risk.

II. Level 2: Basic Assessment

A Level 2 assessment is a detailed visual inspection of a tree and its surrounding site and a synthesis of the information collected. It requires a 360° ground-based inspection around a tree, including the site conditions, visible buttress roots, trunk, branches, and crown.

The Level 2 assessment may include using tools such as binoculars, mallet, or probe at the discretion of the assessor or at the request of the owner/client.

At this level, the assessor may:

1. Locate and identify the tree or trees to be assessed.
2. Determine the targets and target zone for the tree or tree part(s) of concern.
3. Review the site history and conditions, and species failure profile.
4. Assess potential load on the tree and its parts.
5. Assess general tree health.
6. Inspect the tree visually which may include the use of common tools such as binoculars, mallet, probes, and/or shovels, as specified in the Scope of Work.
7. Record observations of site conditions, defects, indicators of internal defects, and response growth.
8. If necessary, recommend a Level 3 advanced assessment.
9. Analyze data to determine the likelihood of failure, likelihood of impact, and consequences of failure to evaluate the degree of risk.
10. Develop mitigation options and estimate residual risk for each option.
11. Recommend a re-inspection interval.
12. Prepare and submit a report.

Limitations: Level 2 assessments only include conditions and defects that can be detected from a ground-based visual inspection on the day of the assessment. Below-ground, internal, or upper-crown conditions, decay, and defects may not be detected.

III. Level 3: Advanced Assessment

A Level 3 assessment is performed to provide detailed information about specific tree parts, defects, targets, or site conditions. These are usually conducted in conjunction with or after a Level 2 assessment with owner/client approval. Specialized equipment, data collection and analysis, and/or expertise are usually required for Level 3 assessments.

At this level, the assessor may:

1. Locate and identify the tree or trees to be assessed.
2. Determine the targets and target zone for the tree or tree part(s) of concern.
3. Review the site history and conditions, and species failure profile.
4. Assess potential load on the tree and its parts.
5. Assess general tree health.
6. Inspect the tree and/or site using advanced techniques as specified in the Scope of Work.
7. Record results from advanced techniques.
8. Analyze data to determine the likelihood of failure, likelihood of impact, and consequences of failure to evaluate the degree of risk.
9. Develop mitigation options and estimate residual risk for each option.
10. Recommend a re-inspection interval.
11. Recommend other advanced assessments, if necessary.
12. Prepare and submit a report.

*Items 1-5 may be included in the associated Level 2 assessment.

Procedures and Methodologies Often Used For Level 3 Assessments

Level 3 procedures and methodologies, which are referred to as technologies, may include:

Procedure	Methodology
Aerial inspection and evaluation of structural defects in upper stems and branches	<ul style="list-style-type: none"> visual inspection from within the tree crown or from a lift unmanned aerial vehicle (UAV) photographic inspection decay testing of branches
Detailed target analysis	<ul style="list-style-type: none"> property value of anything potentially impacted by tree failure use and occupancy statistics potential disruption of activities such as road blockage or an electrical outage
Detailed site evaluation	<ul style="list-style-type: none"> history evaluation soil profile inspection to determine root depth soil mineral and structural testing
Decay and wood analysis	<ul style="list-style-type: none"> increment boring drilling with small-diameter bit resistance-recording drilling single path sonic (stress) wave sonic tomography electrical impedance tomography radiation (radar, X-ray) advanced analysis for pathogen identification
Health evaluation	<ul style="list-style-type: none"> tree ring analysis (in temperate zone trees) shoot length measurement detailed health/vigor analysis starch assessment
Root inspection and evaluation	<ul style="list-style-type: none"> root and root collar excavation root decay evaluation ground-penetrating radar
Storm/wind load analysis	<ul style="list-style-type: none"> detailed assessment of tree exposure and protection computer-based estimations according to engineering models wind reaction monitoring over a defined interval
Measuring and assessing the change in trunk lean	<ul style="list-style-type: none"> visual documentation digital level
Load testing	<ul style="list-style-type: none"> hand pull measured static pull measured tree dynamics

Limitations: Level 3 assessments that include specialized technologies may have uncertainty and require qualified estimations. Exact measures may not be feasible.

Conclusion

Regardless of the level of assessment conducted, every assessment is limited to the trees identified in the scope of work, conditions detectable at the time of the assessment, the level of communication with the owner/client, and other conditions that affect the assessor's ability to collect information. Not all defects and conditions are detectable, and not all tree failures can be predictable. Trees are living organisms, and as such, every tree's structural conditions change over time.