



9 Calvin - Oct. 2, 2024 5-5:30 p.m. Showing filled are from street looking north



Filled area left, silt fence, wetlands right looking north



Slope to silt fence approximately 1 to 2 lower area near wetlands



Further up filled area slope steepens to approximately 1 to 1.



Reverse angle from near top of filled area looking back at street



Wetland beyond silt fence largely undisturbed except for recent tree stump, some invasives noted such as stilt weed and Asian bittersweet

Following photos taken Dec. 9. 2021 10:55a



Looking northerly from street



Looking northwesterly from street across wetlands



Looking northerly at tracking, wood chips and brush in wetlands and fill area